Status: 10|2024

Instructions for use

PAX Sling

EN 354: 2010 / EN 566: 2017 / EN 795-B: 2012

PAX

Instructions for use PAX Slings

The unicoloured PAX webbing slings are available in six different colours.
Every colour is assigned a different length of up to 180 cm and then the
colours begin to repeat with each subsequent size.
The PAX webbing slings are about 25 cm wide and are suitable for self-
attachment, as a binding medium or anchoring in compliance with
EN 354:2010 / EN 566:2017 / EN 795-B : 2012 requirements.

ItemNo.	Item-Name		Colour	Dimensions	
140984203	PAX Sling	40 cm	03	Length:	40 cm
140994210	PAX Sling	60 cm	10	Length:	60 cm
141004201	PAX Sling	80 cm	01	Length:	80 cm
141014208	PAX Sling	100 cm	08	Length:	100 cm
141024239	PAX Sling	120 cm	39	Length:	120 cm
141034202	PAX Sling	150 cm	02	Length:	150 cm
141044209	PAX Sling	180 cm	09	Length:	180 cm
141044203	PAX Sling	180 cm	03	Length:	180 cm
141054210	PAX Sling	200 cm	10	Length:	200 cm

X-CEN-TEK GmbH & Co. KG • Westerburger Weg 30 • D-26203 Wardenburg • Phone: +49 (0)4407-714 76 0 • Fax: +49 (0)4407-714 76 99 • Mail: info@pax-bags.de

2

Instructions for Use - PAX Sling
EN 354: 2010 / EN 566: 2017 / EN 795-B: 2012

Please read this instruction manual carefully.
It's important.

Your PAX Team

General

This user manual describes the intended use of the PAX Sling. This is part of the Personal Protective Equipment for Fall Protection (PPE). Using this product requires that you read and understand the instructions to avoid misuse and any associated hazards or accidents. In order to use the product correctly, you must have appropriate knowledge in handling PPE and the associated risks. This user manual shows only the most important uses and techniques and does not replace PPE user training!

The warnings show you the most important hazards when handling the product.
Keep this manual throughout the life of the product. It must be fully available at all times to the user and the person responsible for personal protective equipment.
These instructions must be provided to the end user by the reseller in the language of the country of destination.

We at PAX recommend the clear assignment of the product to one person.

Safety and liability information

There are risks associated with the handling of personal protective equipment for fall protection and working at heights or working with a risk of falling. Improper use can lead to serious physical damage or even death. You are responsible for your actions and the proper use of this product.
Also observe country specific national and international regulations for handling this product or the PPE.
If you have any doubts about handling the product or you are unwilling to accept the consequences due to potential misuse, do not use this product.
When using PPE, a corresponding risk assessment must be prepared for the use and the activity.
On this basis, appropriate safeguards must be taken and a suitable rescue concept created.
You should be aware that inappropriate physical and/or mental health may result in impaired safety in both normal and emergency situations. The PAX Sling serves solely to secure a person.
Lifting and striking loads is not permitted!

In case of improper use, the company X-CEN-TEK GmbH is not liable!

If you have questions, feel free to contact us.

X-CEN-TEK GmbH & Co. KG • Westerburger Weg 30 • D-26203 Wardenburg • Phone: +49 (0)4407-714 76 0 • Fax: +49 (0)4407-714 76 99 • Mail: info@pax-bags.de

3

Instructions for Use - PAX Sling
EN 354: 2010 / EN 566: 2017 / EN 795-B: 2012

Instructions for use Connector according to EN 354: 2010
When using a connector in the harness system, make sure that the connector - including shock absorbers and connectors - does not exceed a maximum total length of 2.0 m. Connectors must not be attached, shortened or lengthened by knots. Attaching by means of choker hitch is allowed.

ATTENTION! Even suitable knots can reduce the strength of bands and loops by up to 50 percent. The fastener may only be attached to a reliable anchor point, a safety harness or other components of the safety harness system.

Stopping system according to EN 795-B: 2012
Before using the harness system, it is important to ensure that there is the required clear space of 7 meters below the user. The length of the PAX Sling should always be matched to the object it is attached to. The anchor point must have sufficient strength (at least 7.5 kN for one person).

Connection elements for the stopping system according to EN 795-B must comply with EN 362.

ATTENTION! When using together with shock absorbers, care must be taken to ensure that the effectiveness of the overall system is maintained (Consult the instructions for use for the shock absorber!).

General information for selecting the anchor point
To avoid strain and rocking, anchor points must always be as vertical as possible above the person being secured. The PAX Sling should be kept as tight as possible to avoid the band becoming slack. When fixing the PAX Sling to the anchor point, avoid any thing that may reduce stability. Ridges, sharp edges and pinching can greatly reduce the strength of the band. If need be, work with a suitable aid as a base for the anchor point.

Safety Instructions
Before using the PAX Sling together with other rescue or harness systems, the user must be aware of and follow the appropriate recommendations and instructions for use. Use only CE marked components for PPE for Fall Protection together with the PAX Sling. The product must be checked before and after use for possible damage. The condition for use and the ability to function correctly are to be ensured.

ATTENTION! This product should be immediately discarded if there is even the slightest doubt about its safety in use.

The PAX Sling must not be exposed to harmful influences. Including: aggressive substances (e.g. acids, alkalis, oils, petrol, cleaning agents), heat (e.g. the opening of „hot doors", welding flame or sparks, cigarette burns), mechanical influences (e.g. sharp edges). In addition, moisture and especially ice can severely impair the strength of textile products.

ATTENTION! Edge drops should be avoided by taking reasonable precautions.

PAX

Instructions for Use - PAX Sling
EN 354: 2010 / EN 566: 2017 / EN 795-B: 2012

Labelling

CE Label
Instructions for Use

Product Size / Product Breaking Load
Product Name   Manufacture Logo

PAX-Bandschlinge / PAX-Sling	
Length: X,X meters; Tensile strength: 22kN	**PAX** www.pax-bags.com
EN 354:2010 EN 795-B:2012 EN566:2017	
Fabrikationsdatum / Manu.date: yyyy-mm	
CE 2927 **Seriennummer / Serial Number: 0001**	

Serial Number   Manufactured
European Standard   Month/Year

Registration

Product name: PAX Band Sling
CE 2927 - EN 354:2010 / EN 566:2017 / EN 795-B : 2012
The EU Type Examination has been carried out by the notified body No 0161:
AITEX, Plaça Emili Sala, 1
03801 ALCOI – SPAIN.

The supervised control of the product at random intervals (module C2) in accordance with annex VII of Regulation (EU) 2016/425 has been carried out by the notified body No 2927:
QUINTIN CERTIFICATIONS 825 route de Romans 38160 Saint
Antoine L'ABBAYE - FRANCE.

Download link to type approval examination:

https://www.pax-bags.com/go/download/type-ap-band-sling/

![PAX logo]

Instructions for Use - PAX Sling
EN 354: 2010 / EN 566: 2017 / EN 795-B: 2012

Features

Material:	Polyester
Width:	25 mm ±1 mm
Thickness:	1,5 mm ± 1 mm
Minimum Breaking Load:	22 kN

Dimensions			Colour
Length:	40 cm	03	Black
Length:	60 cm	10	Silver
Length:	80 cm	01	Red
Length:	100 cm	08	High-Vis-Yellow
Length:	120 cm	39	Green
Length:	150 cm	02	Blue
Length:	180 cm	09	Orange
Length:	180 cm	03	Black
Length:	200 cm	10	Silver

X-CEN-TEK GmbH & Co. KG • Westerburger Weg 30 • D-26203 Wardenburg • Phone: +49 (0)4407-714 76 0 • Fax: +49 (0)4407-714 76 99 • Mail: info@pax-bags.de

6

Instructions for Use - PAX Sling

EN 354: 2010 / EN 566: 2017 / EN 795-B: 2012

Use and Function

22 kN

2x22 kN

17 kN

12 kN

Use Temperature: -40 - 80 °

Instructions for Use - PAX Sling
EN 354: 2010 / EN 566: 2017 / EN 795-B: 2012

Sharp edge usage

Service Life/Replacement State

PAX Band Straps must not be exposed to harmful influences. These can significantly reduce the strength of textile products and thus represent a considerable safety risk. Use a risk assessment procedure to recognise the hazards for this product. Exclude any danger to the equipment by using suitable protective measures!

Hazards that can significantly limit the service life, strength and function of the product are:
*   Mechanical influences (e.g. sharp edges, abrasions)
*   Contact chemicals (e.g. acids, alkalis, oils, gasoline, cleaning agents, paints, possibly resins)
*   Heat (e.g. flames or sparks, cigarette heat, hot surfaces)
*   Wetness/humidity
*   Extreme cold
*   UV radiation (e.g. sunlight)

The service life depends on the type & frequency of use and storage.
Textile material, in particular made of synthetic, is subject to a certain degree of aging even when not in use.
Service life before first use: 2 years storage.
Service life from first use: 10 years depend on the type & frequency of use and storage.

The maximum usage life is
*   in optimal storage conditions and without use - 12 years,
*   in rare, appropriate use without visible wear, without soiling and
        optimum storage conditions - 10 years,
*   for frequent and intensive or extreme use with frequent loads
        and clearly visible traces of use - a maximum of 1 year.

ATTENTION! After a fall or damage (such as damaged edges, pulled yarns, damage or abrasion to the seams, after exposure to chemicals or extreme heat), you must discard the PAX Sling and replace it.

Instructions for Use - PAX Sling
EN 354: 2010 / EN 566: 2017 / EN 795-B: 2012

Storage
Dry wet/damp PPE before storage and protected it from light.
Do not dry PPE near open flames or hot surfaces.
- Store cool, dry and protected from sunlight.
- Store outside of transport containers.
- No contact with chemical (Caution: battery acid!).
- Store without mechanical crushing, pressure or tensile load.

Transport
- No direct sunlight.
- No contact with chemicals.
- No dirt/dust.
- No mechanical damage.
- Use special transport containers.

Cleaning
- You can clean a dirty PAX Sling in lukewarm water
  with neutral soap if necessary).
- Then rinse well and dry at room temperature.

ATTENTION! Never dry your PPE in tumble dryers or near radiators!

ATTENTION! Never clean your PPE with aggressive substances.

Examination and Repair
As the user, you must check the condition of the PAX Band Sling before use. This also applies to
all other items of Personal Protective Equipment (PPE), in particular the PPE for Fall Protection.

At least every 12 months, the condition of the PAX Sling
(as well as other PPE's) must be checked by a qualified and competent person.

The PAX Sling must be subjected to a careful visual inspection.
The examination results can be entered in the enclosed test card.
If there are any doubts regarding further use, the product should be discarded immediately.

Repairs may only be carried out by the manufacturer or by a person authorized
by the manufacturer.

![PAX logo]

Test Card

This test card must be completed in full by a PPE expert during the annual expert examination.
This checklist does not claim to be entirely complete and the expert must make their own decision on the overall condition.

Product Name:	PAX Sling		Purchase Date:	
Serial Number:			Date of First Use:	
Manufacture Date:			Remove Product from Service on:	

Year	Date	Name & Signature of Qualified Person	Detected damage	Band undamaged	Seams undamaged	No chemical contamination	Label readable	Instructions	Passed	FAILED	Measures
1.											
2.											
3.											
4.											
5.											
6.											
7.											
8.											
9.											
10.											
11.											
12.											

The test card is available as a download for printing and for completing in full
under the following download link: https://www.pax-bags.com/go/BSpk-en

X-CEN-TEK GmbH & Co. KG • Westerburger Weg 30 • D-26203 Wardenburg • Phone: +49 (0)4407-714 76 0 • Fax: +49 (0)4407-714 76 99 • Mail: info@pax-bags.de

10

X-CEN-TEK GmbH & Co. KG

Westerburger Weg 30
26203 Wardenburg
Germany

Phone: +49 44 07 - 7 14 76 - 0
Fax: +49 44 07 - 7 14 76 - 99
Mail: info@pax-bags.de

www.pax-bags.com